

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES BRANCH

RECORD OF WELL

1. Location: State New York County Putnam
Nearest P. O. Dijkeman Direction from P. O. S
Distance from P. O. 1 1/2 miles; 15.55 7.2 E 15 Y
15' quab

If in city, give street and number Town of Southeast
Bertha & Helen Verberacker

2. Owner: Lake View Manor Address Zonetta Lake, N.Y.
Driller: Frank Bacon Address Danbury Conn.

3. Situation: Is well on upland, in valley, or on hillside? hillside near lake valley

P96 P247

<u>15 Y</u>	<u>15.55</u>
<u>7.2 E</u>	<u>5.5 S</u>

Locate well on plat of section.

Drilled by Dougherty (2-10-48)
and from driller 6-5-50

and any other facts not given above.

6-9642

Name of person filling blank V. H. R. from N.Y.
Date 6-5-50 Address St. Grossen

On the back of this sheet give the record of the beds through which the well passes

LOG OF WELL

KIND OF ROCK OR OTHER MATERIAL (Give color and tell whether hard or soft)	DEPTH, IN FEET		THICKNESS, IN FEET	REMARKS (Especially information as to water found)
	From—	To—		
Loam	0	2	2	
Hardpan	2	12	6	
Yellow clay	12	18	6	
Blue clay	18	38	20	
Granite & "quartzite"	40	85	45	no water
Soft black gr rock	85	90	5	water
Rock	90	143	53	
<hr/>				
Well seal cement	1	1	2	3
Pumping tests - <u>not</u> by Frank Bacon				
Static water level in ft. below grade	18	18	18	"probably by plumber,
Pumping rate in GPM	2	2	2	- F. Bacon.
Pumping level in ft. below grade	85	110	140	
Duration of test in hours	3	3	3	
<hr/>				
Bailer tested at 3 GPM by Frank Bacon for 2 hours with 130' of drawdown.				